

• **Hollow Drive Shaft** - 4ft. (1.2m) long aircraft quality steel shafts to connect to drive.

Model **DS-300 to DS-500**

Model **DS-562 to DS-750**

• **Hollow Driven Shaft** - 4ft. (1.2m) long aircraft quality steel shafts to connect to driven shafts. Order quantities based on length of tube to be cleaned.

Model **DN-300 to DN-500**

Model **DN-562 to DN-750**

• **Drive Coupling** - To Couple hollow drive shaft to drive.

Model **DC-300 to DC-500**

Model **DC-562 to DC-750**

• **Shaft Coupling** - To Couple 2 hollow shafts together.

Model **SC-300 to SC-500**

Model **SC-562 to SC-750**

• **Starter Drill** - To make pilot holes in deposits of completely clogged tubes.

Model **SD-312 to SD-500**

Model **SD-562 to SD-750**



Tube I.D.'s suited for mm	Tube I.D.'s suited for inch	Drive Model No.	Hollow Drive Shaft Model No.	Hollow Driven Shaft Model No.	Drive Coupling Model No.	Shaft Coupling Model No.	Starter Drill Model No.
4.8-6.4	3/16-1/4	C-10	DS-300	DN-300	DC-300	SC-300	-
9.5	3/8		DS-312	DN-312	DC-312	SC-312	SD-312
11.1	7/16		DS-375	DN-375	DC-375	SC-375	SD-375
12.7-14.3	1/2-9/16		DS-437	DN-437	DC-437	SC-437	SD-437
15.9-17.5	5/8-11/16		DS-500	DN-500	DC-500	SC-500	SD-500
19.1-20.6	3/4-13/16		DS-562	DN-562	DC-562	SC-562	SD-562
22.2-25.4	7/8-1	CP-315	DS-625	DN-625	DC-625	SC-625	SD-625
27.0-51.0	1.1/16-2		DS-750	DN-750	DC-750	SC-750	SD-750

**CLEANING TOOLS
FOR USE WITH PORTABLE PNEUMATIC TUBE CLEANERS**

- **Nylon Brushes** - Refer to pages 100, 103
- **Brass Brushes** - Refer to pages 100, 103
- **Stainless Brushes** - Refer to pages 100, 103
- **Buffing Tools** - Refer to pages 101, 105
- **Carbide Drills** - Refer to pages 101, 105



PORTABLE PNEUMATIC TUBE CLEANING KITS



Build your own kit by adding price of Drive (C-10 or CP-315), Hollow Drive Shafts, Hollow Driven Shafts, Shaft Couplings, Drive Coupling based on length of tube to be cleaned and cleaning tools (Brushes, Carbide Drills, Buffing Tools).

We will supply all the above in a handy box at no extra charge ! The box will accomodate a maximum of 1 Drive + 4 Hollow Shafts + 5 Couplings + 18 Cleaning Tools (Brushes, Carbide Drills, Buffing Tools).